

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1551  
East  
> 1  
1.959 mi.  
10342 ft.

**SANDY FOLLOW UP**  
**131 KENSINGTON STREET**  
**BROKLYN, NY**

**NY Spills** **S112229200**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**2 ft.**

**SPILLS:**

Name: SANDY FOLLOW UP  
Address: 131 KENSINGTON STREET  
City,State,Zip: BROKLYN, NY  
Spill Number/Closed Date: 1209071 / 2013-06-28  
Facility ID: 1209071  
Facility Type: ER  
DER Facility ID: 426389  
Site ID: 472134  
DEC Region: 2  
Spill Cause: Storm  
Spill Class: C3  
SWIS: 2401  
Spill Date: 2012-11-04  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2012-11-04  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2012-11-04  
Spill Record Last Update: 2013-06-28  
Spiller Name: GILVA MANGRACCHIA  
Spiller Company: STORM DAMAGE  
Spiller Address: 131 KENSINGTON STREET  
Spiller Company: 999  
Contact Name: GILVA MANGRACCHIA  
DEC Memo: "Tanks filled in May. Nominal amount used for domestic hot water since. Power company will not re-energize home until oil in basement has been removed. Try both phones. \*\* This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts.\*\* Inspected the site on 06/26/13, no body was home, did not have access to the basement. Phone no does not work.(sr)"  
  
Remarks: "storm damage - clean up pending unknown amount oil mixed w/water. House phone number 718.769.1312."

**All Materials:**

Site ID: 472134  
Operable Unit ID: 1221990  
Operable Unit: 01  
Material ID: 2220658  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 400.00



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Units: G  
Recovered: .00  
Oxygenate: Not reported